

HEAT PRO gloves



Distributed by:



Body protection: aluminised clothing

Description and composition:

Aluminised suede gloves (cowhide) orange coloured palms: Level 2 cut resistance.

Rest of the glove in aluminised para-aramid. Inner lining 100% cotton: soft and comfortable.


This combination of materials provides resistance to heat, perforation and a great dexterity in handling pieces.

The pieces are sewn together with Kevlar thread, resistant to high temperatures.

Sizes: 8, 9, 10 and 11.



Suede palm: Anti-cut 2



Aluminised fabric



Sewn with Kevlar thread

Category III

Ref:	Size	MEASUREMENTS			
		Α	В	C	D
912318	8	41	19,5	12,5	18
912311	9	42	20,5	13	19
912310	10	43	20,5	13,5	20
912319	11	44	22	14,5	21



v 1 2 3 4	Resistance to abrasion (palm)
Mechanical Wechanical Wechanical Wechanical Wechanical Wechanical Wechanical Websites Website	Resistance to blade cuts (palm)
1 2 3 4	Tearing (palm)
≥ 1 2 3 4	Perforation (palm)
1 2 3 4	Flame resistance (palm and back)

1 2 3 4	Flame resistance (palm and back)
\$\frac{1}{2} \frac{3}{3} \frac{4}{4}	Contact heat (palm)
	Convective heat (palm)
1 2 3 4	Radiant heat (back)
£ 1 2 3 4	Small splashes of molten metal (back)
1 2 3 4	Large splashes of molten metal (back)

Body protection: aluminised clothing

Standard and certification		89/686/CEE directive, transposed in Royal Decree 1407/1992, according to regulations UNE-EN 420:2004+A1:2010+ERRATUM 2011, UNE-EN 388:2004 and UNE-EN 407:2005.			
Applications	Specially recommended for workstations with a higher risk of abrasion and ones that require more dexterity when handling objects. Highly appropriate for handling pieces at 100 °C for long periods. They protect against spillage and small splashes of molten metal. PPE for industrial use: foundries, metal industry, pyrotechnics, furnace repair, cement works, steelworks etc.				
Conservation Storage - Expiry	Do not store near chemical contaminants nor when the fabric is wet. Avoid exposure to daylight. Store in a dry, well ventilated, place. If the gloves get wet, dry in a well ventilated place.				
Directions Use	Correct performance of the garment requires it to be correctly adjusted. This equipment is for personal use and should not be used by several people. For safety reasons, always carry out a visual inspection of the product before use.				
Presentation	Individually packed: 1 pair 50 unit carton Carton size: 45 x 41.5 x 35.5				
Bar code					
	Box bar code Carton bar code Size 8 8423173884321 584231738843	26 Cofe			
	Size 9 8423173884260 584231738842				
	Size 10 8423173884253 584231738842	65 58 WE PROTECT			
	Size 11 8423173884338 584231738843.	33			

